

From: Gary Heine/=TMS/Toyota.

Sent:9/18/2008 3:53 PM.

To: [ - ] Tom Steger/=TMS/Toyota@Toyota; Clayton Meyer/=TMS/Toyota@Toyota; Cole Stutz/=TMS/Toyota@Toyota; Andrew Curtin/=TMS/Toyota@Toyota; Mike Robinson/=Mobile/Toyota@Toyota; Jaime Angulo/=TMS/Toyota@Toyota; Craig Parker/=TMS/Toyota@Toyota; John Stover/=TMS/Toyota@Toyota; Tim Davis/=TMS/Toyota; Nobu Takeda/=TMS/Toyota@Toyota; Scott Stewart/=TMS/Toyota; Kirk Forsht/=TMS/Toyota@Toyota; Austin Fadel/=TMS/Toyota@Toyota.

Cc: [ - ] .

Bcc: [ - ] .

Subject: Fw: Toyota PQSS Executive Summary through September 13, 2008.

Regards,  
Gary Heine  
Quality Assurance Powertrain Manager  
Toyota Customer Services Division  
O- 310 468 2521  
C- 310 977 0860  
F- 310 381 7783

----- Forwarded by Gary Heine/TMS/Toyota on 09/18/2008 03:52 PM -----

"Colacurcio, Joe" <Joe.Colacurcio@nielsen.com>

09/18/2008 03:37 PM

To <greg\_bryan@toyota.com>, <gordon\_rush@toyota.com>

cc "Randy\_Wagner@toyota.com" <'Randy\_Wagner@toyota.com'>, "Jeff\_Northrup@toyota.com"

<'Jeff\_Northrup@toyota.com'>, "craig\_erickson@toyota.com" <'craig\_erickson@toyota.com'>,

"matt\_allen@toyota.com" <'matt\_allen@toyota.com'>, "brian\_lyons@toyota.com" <'brian\_lyons@toyota.com'>,

"Randy\_Reida@toyota.com" <'Randy\_Reida@toyota.com'>, "Howard\_Abrahams@toyota.com"

<'Howard\_Abrahams@toyota.com'>, "Russell\_Suzuki@toyota.com" <'Russell\_Suzuki@toyota.com'>,

"Mike\_Robinson@toyota.com" <'Mike\_Robinson@toyota.com'>, "Gary\_Heine@toyota.com"

<'Gary\_Heine@toyota.com'>, "Bob\_Nagai@toyota.com" <'Bob\_Nagai@toyota.com'>, "Tom\_Krembs@toyota.com"

<'Tom\_Krembs@toyota.com'>, "michael\_jarboe@toyota.com" <'michael\_jarboe@toyota.com'>,

<Tom\_Kim@toyota.com>, <Charles\_Lee@Toyota.com>, <glen\_fujita@toyota.com>, <ruben\_nieto@toyota.com>,

"Enzweiler, Julie" <Julie.Enzweiler@nielsen.com>, "Stephenson, Bill" <Bill.Stephenson@nielsen.com>, "Black,

Larry" <Larry.Black@nielsen.com>, "Patak, Elizabeth" <Elizabeth.Patak@nielsen.com>, "Hamm, Scott"

<Scott.Hamm@nielsen.com>

Subject Toyota PQSS Executive Summary through September 13, 2008

Hello,

Attached please find the Toyota Quality Executive Summary report reflecting data from August 31st, 2008 – September 13th, 2008. The reporting site (<http://toyota.reports.buzzmetrics.com/main.asp>) has also been updated with the latest information.

Toyota

4Runner Current Generation

§ Driver's Seat Problems

Avalon Current Generation

§ Tire Wear and Noise

Camry Current Generation

· Transmission Shifts and TSB

· Moonroof and Seatbelt Rattles

· Fluctuating Volume from Rear Speakers

· Vibrations Throughout Car

· Warped Front Rotors

· Water Leak

· Alignment Issue, Rough Ride

Camry Hybrid Overall

- Trouble Starting
- Paint Chips
- Camry Solara Overall
- Convertible Top Odor
- Corolla Current Generation
- § JBL and Standard Stereo Issues
- § General 2009 Corolla Complaints
- § Paint Problems
- § Poor Braking Performance
- § Engine Knocking/Tapping Noise
- § Manual Transmission Issues/Questions
- § Interior Rattles
- Matrix Current Generation
- § Heat Affects XM Satellite Radio Buttons
- Prius Current Generation
- § Braking Problems
- § Vehicle Stuck in Park
- § Steering Problems
- § Starting Problems
- § Overheating in Traffic
- § MFD/Bluetooth Issues
- § Headlight Problems
- Prius Previous Generation
- § HV/Traction Battery Failure
- RAV4 Current Generation
- § Steering Clunk
- RAV4 Current and Previous Generation
- § Unexpected Airbag Deployment
- Sienna Current Generation
- § Sliding Door Problems
- § Air Conditioning Failures
- § 3.5L V6 Engine Noise/Knock
- § iPod/AUX Interference
- Tacoma Current Generation
- Manual Transmission/Clutch Problems
- Engine Grinding/Ticking Noises
- Vehicle "Surge"
- Paint Problems
- Tacoma Previous Generation
- Frame-Rust/Buy-Back
- Tundra Current Generation
- § Wheel Paint and Numerous Problems
- § Poor Paint Quality
- § Transmission Shudder
- § 5.7L V8 Rocker Arm/Lifter Failure
- § Radio Problems
- Tundra Previous Generation
- § Potential Rust Issues
- Yaris Overall
- Passenger Seatbelt and Airbag Warning Lights
- Lexus
- ES 350 Overall
- Paint Issues
- Trunk Alignment
- GS 300 Overall
- Interior Water Leak and TSB
- Hesitation and Rough Shifting
- Brakes Lock-Up Under Hard Braking
- IS 350 Overall
- Engine Noise Upon Start-Up, TSB
- Broken Brake Caliper

IS-F Overall

- Delayed Downshifts

RX 350 Overall

- Cruise Control Shifting Up and Down Hills

RX 400h Overall

- Emissions Test Failure

- iPhone and Parrot Bluetooth Car Kit Use

Scion

Scion xB Current Generation

- Windshield Crack

- Paint Chipping

Please let us know if you have any questions.

Thanks,

Joe Colacurcio

Senior Analyst, Automotive

Nielsen Online

The Nielsen Company

50 West RiverCenter Blvd.

Third Floor

Covington, KY 41011

859.905.4936 voice

610.462.3048 mobile

joe.colacurcio@nielsen.com

www.nielsen-online.com